## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

Ù

Top view of a typical magnetic head arm assembly (HAA)




Figure 1

Prior Art

Figure 2

Fig. 2b


Residual Stress


214

206 -


Prior Art

322.652 10442 20560 30679 40798 50917 61036 711155 81274 91393





BEST AVAILABLE COPY



Actuator coil assembly

Figure 7